	XYZ / Winterville - Survey Dates: 5th July to 10th July						URGENT		
Count	*Plant Location*	*Asset Number*	*Equipment*	*TAG*	*dB*	*Code*	*Fault Description*	*Comment*	*Work No.*
1	Lower Service Area		damaged pushlock joiner inside cage - out feed end	53	100+	zrpf	Replace pushlock fitting	Very Urgent, unable to access	
2	Lower Service Area		large leak inside cabinet under feed table pressure gauge	51	100	zrr	Repair or Replace	Urgent, unable to access	
3	Lower Service Area		solenoid valve block on top deck out feed	54	80+	zrr	Repair or Replace	Urgent, multiple leaks	
4	Plant Room 206		VDSV 2	11	85+	zrr	Repair or Replace	Urgent -Gauge missing off end of line	
5	Plant Room 206		air supply to regulator	7	100	ztc	Tighten Clamp	Urgent -air line held tight	
6	Plant Room 106		feed out end rollers below movable stop	38	100+	zrr	Repair or Replace	Urgent - tear in air bag	
7	Lower Service Area		1B27 Air Cylinder - top deck	56	100	zrarns	Replace air ram neck seal	Urgent	
8	Lower Service Area		main air supply to valve body - top deck	59	85+	zts	Thread Seal	Urgent	
9	Lower Service Area		drive side tamper cylinder in feed	60	100+	zrv	Rekit Valve	Urgent	
10	Lower Service Area		air blower - full pressure on 6mm airline - on continuously, query isolate when machine not in use or smaller air line		100+	zrr	Repair or Replace	Urgent	
11	Main Machine Room		rear cable tray above roller #1 - air line joiner	79	80+	zrpf	Replace pushlock fitting	Urgent	
12	Main Machine Room		double backer glue section - tear in air bag - operator side	80	100+	zrr	Repair or Replace	Urgent	
13	Plant Room 106		tamper cylinder on in feeder	45	100	zrv	Rekit Valve	Urgent	
14	Plant Room 206		regulator assemble	8	80+	zrcb	Replace cracked bowl	Urgent	
15	Plant Room 206		hose line to air tool - drive side	9	100+	ztc	Tighten Clamp	Urgent	
16	Plant Room 206		Unit #4 paint pump	10	100+	zvec	Valve Exhausting Continuously	Urgent	
17	Service Floor		query solenoid valve inside cabinet #4	23	80+	zvec	Valve Exhausting Continuously	Urgent	